


XL-Saw Replacement Motor Cable

Part # CE-0014 Available on www.tctautomation.com

Splice Cable into Junction Box on Top of Carriage Using Wire Nuts, Leave Plenty of Slack!

Mount Junction Box Securely and Confirm There is No Interference in Carriage Travel or Lead Screw



Route Cable Along Original Path. Loop Cable and Add Zip Tie to Prevent Slippage.

Use Wire Nuts Inside Motor Box. Replace Cover Securely.

Updated: March 27th, 2017