




XL-SAW SERVO WIRING

Function	Pin
Thermal Switch	A
Thermal Switch	B
Brake	C
Brake	D
U	1
Ground	2
W	3
V	4

8 Pin



Connector Termination



J8